OMB No.: 3150-0011 NRCB 87-02. Supplement 1

## UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF NUCLEAR REACTOR REGULATION WASHINGTON, D.C. 20555

April 22, 1988

NRC BULLETIN NO. 87-02, SUPPLEMENT 1: FASTENER TESTING TO DETERMINE CONFORMANCE WITH APPLICABLE

MATERIAL SPECIFICATIONS

### Addressees:

All holders of operating licenses or construction permits for nuclear power reactors.

### Purpose:

The purpose of this supplement is to require addressees to submit additional information on the source of fasteners purchased for use in nuclear power plants.

## Description of Circumstances:

Item 5 of NRC Compliance Bulletin 87-02 requested that all holders of operating licenses or construction permits for nuclear power reactors submit information regarding the identity of the suppliers and manufacturers of the safety-related and non-safety-related fasteners selected for testing. After further consideration, the NRC has determined that it needs information regarding the identity of all vendors from which safety-related and non-safety-related fasteners have been obtained within the past 10 years, a reasonable period which will not put undue burden on addressees. This information will assist the NRC in determining whether nuclear facility fasteners in use have been supplied in accordance with their intended use. In addition, this information is needed so that the NRC can properly coordinate information with other government agencies concerned with problems identified in the quality of fasteners.

# Action Required:

Within 90 days from the receipt of this supplemental bulletin, addressees shall provide the following information concerning the procurement of fasteners within the past 10 years:

A list of the suppliers and manufacturers from which safety-related 1. fasteners have been purchased, including addresses, and the type of fasteners purchased (i.e., the material specifications). For those fastener purchases made from fastener suppliers and/or original equipment manufacturers, any available information concerning the manufacturer or sub-tier supplier of the fastener also should be provided.

2. For non-safety-related fasteners the same information as requested in item 1.

The written reports requested above shall be addressed to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555, under oath or affirmation under the provisions of Section 182a, Atomic Energy Act of 1954, as amended. In addition, a copy shall be submitted to the appropriate Regional Administrator.

This requirement for information was approved by the Office of Management and Budget under a blanket clearance number 3150-0011. Comments on burden and duplication may be directed to the Office of Management and Budget, Reports Management, Room 3208, New Executive Office Building, Washington, D.C. 20503.

If you have any questions about this matter, please contact one of the technical contacts listed below or the Regional Administrator of the appropriate regional office.

Charles E Rossi, Director

Division of Operational Events Assessment Office of Nuclear Reactor Regulation

Technical Contacts: J. T. Conway, NRR

(301) 492-0978

E. T. Baker, NRR (301) 492-3221

Attachment: List of Recently Issued NPC Bulletins

## LIST OF RECENTLY ISSUED NRC BULLETINS

Bulletin	Subject	Date of Issuance	Issued to
No.	Subject	133danec	
88-03	Inadequate Latch Engagement in HFA Type Latching Relays Manufactured by General Electric (GE) Company	3/10/88	All holders of OLs or CPs for nuclear power reactors.
88-02	Rapidly Propagating Fatigue Cracks in Steam Generator Tubes	?/5/88	All holders of OLs or CPs for <u>W</u> -designe nuclear power reacto with steam generator having carbon steel support plates.
88-01	Defects in Westinghouse Circuit Breakers	2/5/88	All holders of OLs or CPs for nuclear power reactors.
87-02	Fastener Testing to Determine Conformance with Applicable Material Specifications	11/6/87	All holders of OLs or CPs for nuclear power reactors.
87-01	Thinning of Pipe Walls in Nuclear Power Plants	7/9/87	All licensees for nuclear power plants holding an OL or CP.
86-04	Defective Teletherapy Timer That May Not Terminate Dose	10/29/86	All NRC licensees authorized to use cobalt-60 teletherapunits.
86-03	Potential Failure of Multiple ECCS Pumps Due to Single Failure of Air-Operated Valve in Minimum Flow Recirculation Line		All facilities holding an OL or CP.
86-02	Static "O" Ring Differential Pressure Switches	7/18/86	All power reactor facilities holding an OL or CP.
86-01	Minimum Flow Logic Problems That Could Disable RHR Pumps	5/23/86	All GE BWR facilitinolding an OL or CP

OL = Operating License CP = Construction Permit

For non-safety-related fasteners the same information as requested in 2. item 1.

The written reports requested above shall be addressed to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555, under oath or affirmation under the provisions of Section 182a, Atomic Energy Act of 1954, as amended. In addition, a copy shall be submitted to the appropriate Regional Administrator.

This requirement for information was approved by the Office of Management and Budget under a blanket clearance number 3150-0011. Comments on burden and duplication may be directed to the Office of Management and Budget, Reports Management, Room 3208, New Executive Office Building, Washington, D.C. 20503.

If you have any questions about this matter, please contact one of the technical contacts listed below or the Regional Administrator of the appropriate regional office.

> Charles E. Rossi, Director Division of Operational Events Assessment Office of Nuclear Reactor Regulation

Technical Contacts: J. T. Conway, NRR

(301) 492-0978

E. T. Baker, NRR (301) 492-3221

Attachment: List of Recently Issued NRC Bulletins

\*SEE PREVIOUS CONCURRENCES

\*D/DOEA:NRR

\*C/OGCB:DOEA:NRR

\*PPMB:ARM

**CERossi** 02/18/88 CHBerlinger 02/18/88

TechEd 02/11/88

\*OGCB:DOEA:NRR \*VIB:DRIS:NRR

JTConway

EBaker

**JStone** 

\*SC/VIB:DRIS:NRR \*A/C/VIB:DRIS:NRR \*D/DRIS:NRR JGPartlow

JERamsev 02/11/88

02/11/88

02/11/88

02/16/88

02/17/88

NPCB 87-02, Supplement 1 February xx, 1988 Page 2 of 2

The written report shall be submitted to the appropriate Regional Administrator under oath or affirmation under provisions of Section 182a, Atomic Energy Act of 1954, as amended. In addition, the original of the cover letter and a copy of the report shall be transmitted to the U.S. Nuclear Regulatory Commission, Document Control Desk, Washington, D.C. 20555 for reproduction and distribution.

This request for information was approved by the Office of Management and Budget under a blanket clearance number 31500011. Comments on burden and duplication may be directed to the Office of Management and Budget, Reports Management, Room 3208, New Executive Office Building, Washington, D.C. 20503.

If you have any questions about this matter, please contact one of the technical contacts listed below or the Regional Administrator of the appropriate regional office.

> Charles E. Rossi, Director Division of Operational Events Assessment Office of Nuclear Reactor Regulation

Technical Contacts: J. T. Conway, NRR

(301) 492-0978

E. T. Baker, NRR (301) 492-3221

Attachment: List of Recently Issued NRC Bulletins

02/11 /88

DRIS:NRR

SC/VIB:DRIS:NRR **EBaker** 02/11/88

PPMB:ARM

C/OGCB: DOEA: NR TechEd CHBerlinger

02///88 02//8/88

A/C/VIB: DRIS: NRR
JStone 02/16/88

D/DRIS:NRR JGPart1ow